

This report provided free of charge by:

Bridge City Motors 1321 NW 17th Ave, Portland, OR 97209

(503) 444-0568



Vehicle History Report[™]

US \$39.99

2014 HONDA ODYSSEY EXL

VIN: 5FNRL5H66EB135562 VAN 3.5L V6 F SOHC 24V GASOLINE FRONT WHEEL DRIVE

This CARFAX Report Provided by:

Bridge City Motors



No accidents or damage reported to CARFAX



2 Previous owners



At least 1 open recall



9 Service history records



Danaanaliiala



Personal vehicle



97,115 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/23/21 at 2:48:23 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🚨 Owner 1	A Owner 2
Year purchased	2014	2020
Type of owner	Personal	Personal
Estimated length of ownership	5 yrs. 8 mo.	11 months
Owned in the following states/provinces	Oregon	Oregon
Estimated miles driven per year	17,232/yr	
Last reported odometer reading	97,115	


CARFAX Title History CARFAX guarantees the information in this section	🊨 Owner 1	🍰 Owner 2
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem


GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle

CARFAX Additional History Not all accidents / issues are reported to CARFAX	🚨 Owner 1	A Owner 2
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Honda dealer to obtain more information about this recall.	Recall Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Detailed History

Owner 1 Purchased: 2014			Personal Vehicle 17,232 mi/yr
Date N	Mileage	Source	Comments
07/24/2014		Wilsonville Honda Wilsonville, OR 503-218-4844 wilsonvillehonda.com 4.7 / 5.0	Vehicle offered for sale
		266 Verified Reviews	
		Customer	
		2,910 Favorites	
08/24/2014	29	Wilsonville Honda Wilsonville, OR 503-218-4844 wilsonvillehonda.com 4.7 / 5.0	Vehicle sold
		266 Verified Reviews	
		Customer	
		2,910 Favorites	
08/24/2014		Oregon Motor Vehicle Dept. Estacada, OR	Titled or registered as personal vehicle





03/07/	2018
--------	------

American Honda Motor Co.

Manufacturer Safety-related recall issued

- NHTSA #18V-170
- Recall #X0R 2014-16 Ody Left (Driver) 2nd Row Seat
- Recliner Safety Recall
- Status: Remedy Available

Locate an authorized Honda dealer to obtain more information about this recall

- Learn more about this recall

Description: American Honda Motor Co., inc. (Honda) is recalling certain model year 2014 - 2016 Odyssey vehicles. The second row outboard seats have levers for the walk-in feature which folds the seatback and slides the seat forward for access to the third row seat. Due to a manufacturing error, if the walk-in lever is used to fold a fully reclined left (drivers side) outboard seatback forward, the seatback recliner mechanism may malfunction, allowing the seatback to stay in the unlocked position or unexpectedly unlock without using the walk-in or recliner lever. This recall is separate from NHTSA Recall 17V-725, which also involves the functioning of the second row left (drivers side) outboard seat, and involves different seat components and functions. The repair for 17V-725 (installation of a bracket on the rear outboard strikers) will not resolve this recall; both recall repairs need to be conducted on your vehicle.

An unlocked second row left outboard seatback increases the risk of injury to the seats occupant during a crash.

Remedy: Please call any authorized Honda dealer and make an appointment to have your vehicle repaired. Your dealer will check for proper operation of the second row left outboard seatback recliner. If operating properly, a support bracket will be added to the seatback recliner to ensure locking/unlocking functionality. If the seatback cannot lock, the seatback frame assembly will be replaced. Support bracket installation or seatback frame replacement, if necessary, will be completed for free. For additional questions or to get help locating a dealer, owners may contact American Hondas Customer Support & Campaign Center at 1-888-234-2138. Hondas number for this recall is XOR.

O3/07/2018

American Honda Motor Co.

Manufacturer Safety-related recall issued
- NHTSA #17V-725
- Recall #P0Q 2nd Row Outer Seat Striker Bracket
- (Seat Tipping)
- Status: Remedy Available

Locate an authorized Honda dealer to obtain more information about this recall
- Learn more about this recall

Description: American Honda Motor Co., inc. (Honda) is recalling certain model year 2011 - 2017 Odyssey vehicles. The second row outer (outboard) seats can be placed in two positions, standard and wide. When installing or repositioning the seat into either position, it is possible that the rear latch may not attach properly to the correct position on the seat striker.

An unlatched second row outer seat could tip forward during moderate to heavy braking increasing the risk of injury to an occupant, including a child seated in a LATCH child seat.

Remedy: Honda will notify owners in an interim notification that the parts necessary to repair their vehicles are currently not available. Included in the interim notification will be detailed instructions for installing/positioning second row outer seats and confirming that they are securely latched. These instructions can also be viewed on www.recalls.honda.com. Honda will send a second notification to owners when parts become available to repair their vehicles and dealers will install a bracket to the second row forward outboard floor strikers to prevent improper seat positioning, apply a warning label to the second row outboard seats and provide an updated owners information card for free. For additional questions or to get help locating a dealer, owners may contact American Honda's Customer Support & Campaign Center at 1-888-234-2138. Honda's number for this recall is POQ.

08/24/2018	Oregon Inspection Station	Passed emissions inspection
09/12/2018	Oregon Motor Vehicle Dept. Oregon City, OR Title #1426261071	Registration issued or renewed
03/26/2020	Oregon Motor Vehicle Dept. Oregon City, OR Title #1426261071	Registration issued or renewed - Loan or lien reported - Registration updated when owner moved the vehicle to a new location

04/11/2020	97,115	Interstate National Dealer Services Lake Oswego, OR inds.com	Service contract issued
05/07/2020		Oregon Motor Vehicle Dept.	Vehicle purchase reported
05/08/2020		Oregon Motor Vehicle Dept. Oregon City, OR Title #OR0001493304	Title issued or updated - Loan or lien reported
06/12/2020		Oregon Motor Vehicle Dept. Lake Oswego, OR Title #OR0001504083	Vehicle purchase reported - Registration issued or renewed

	ner 2 chased: 2020			Personal Vehicle
Date	Mileage	Source	Comments	
07/06/20	020	Oregon Motor Vehicle Dept. Lake Oswego, OR Title #OR0001504083	Title issued or updated - New owner reported	
06/09/20)21	Oregon Motor Vehicle Dept. Lake Oswego, OR Title #OR0001504083	Registration issued or renewed	

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

@ 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 6/23/21 2:48:23 PM (CDT)

have reviewed and received a co FNRL5H66EB135562), which is	py of the CARFAX Vehic based on information su	le History Report for this 2014 HONDA pplied to CARFAX and available as of	A ODYSSEY vehicle (VIN: 6/23/21 at 3:48 PM (EDT).
Customer Signature	Date		Date